

City of Sandpoint, Documented Water System Leaks (2014-2018)							
Date	Location	Type	Pipe size/type	Depth (ft)	Nature/Cause	Material/Parts Used	Backfill
2018							
12/7/2018	1106 Elm	Main	6" cast	5	earthquake	6" Romac full circle wrap	3/4 minus
11/23/2018	510 S 2nd	Service	3/4 galv nip	3.5	pinhole/deterioration	replace parts with brass	topsoil
11/19/2018	1407 Main	Service	1" galv nip	5	pinhole/deterioration	replace parts with brass	topsoil
11/16/2018	712 Larch	Main	6" cast	5	circumferential	6" Romac full circle wrap	
11/16/2018	1st & Main (Kootenai)	Main	6" cast	6	circumferential	6" Romac full circle wrap	3/4 minus
11/11/2018	151 Van Horn Ave	Service	3/4" galv	5	pinhole/deterioration	3/4 wrap	3/4 minus
11/6/2018	610 S Olive	Service	3/4" galv	5	pinhole/deterioration	3/4 wrap	topsoil
11/1/2018	3200 GN Road	Main	18" Coal tar steel	5	pinhole	weld boiler plugs in	3/4 minus
10/29/2018	2015 Sandpoint West Dr	Service	2" galv/pvc	4.5	spilt	replace with 2" cts poly	topsoil
10/23/2018	539 S Ella	Service	3/4 galv	4.5	pinhole/deterioration	replace line with poly	flowfill
10/18/2018	309 Main St	Service	3/4" galv	5	Galv line to park	Needs replaced	topsoil
10/16/2018	1505 Northshore	Service	1" Poly	5	contracor/boring	repace section of line	
10/6/2018	612 S Olive	Service	3/4 galv	5	pinhole/deterioration	2 3/4 wraps	topsoil
9/27/2018	202 Jefferson	Service	LID	6	pinhole/deterioration	turn off curb stop	3/4 minus
9/27/2018	CO-OP	Fire line	6x8 tap saddle	5.6	loose bolts	Tighten bolts on saddle	topsoil
9/26/2018	1707 Westwood Dr	Service	2" sch 40	5	boring for fiber	replace with PVC	topsoil
9/25/2018	1415 Mathison	Service	3/4 galv	5	pinhole/deterioration	replace with brass	topsoil
9/19/2018	1512 Madison	Service	3/4 pvc & galv	6	pinhole/deterioration	replace with brass	flowfill
9/14/2018	1111 Larch	Service	3/4 galv	5	pinhole/deterioration	Wrap/ replace line later date	3/4minus
8/28/2018	1804 Main	Service	3/4" gal parts	4	pinhole	replace with brass	topsoil
8/20/2018	708 Creek side	Service	1" galv nip	4.5	pinhole/deterioration	replace with brass	topsoil
8/14/2018	512 Pine	Service	3/4 galv	3.5	pinhole/deterioration	3/4 wrap	topsoil
8/7/2018	821 Poplar	Service	3/4" galv	5	pinhole/deterioration	replace line with poly	flowfill
8/6/2018	546 Lavina	Service	3/4" galv	5	pinhole/deterioration	replace line with poly	flowfill
7/31/2018	1220 Superior	Service	3/4" galv	5	pinhole/deterioration	replace line with poly	flowfill
7/25/2018	WWTP	Service	1 1/2 galv	2.5	pinhole/deterioration	new parts	dirt
7/23/2018	GN/Gooby	Service	2" galv parts	5.5	contractor Railrod	replace galv parts/curb stop	spoils
6/21/2018	1600 Westwood Dr.	Service	2" galv parts	4.5	pinhole	replace with brass	topsoil
6/19/2018	503 S. Marion	Service	1" CTS poly	4	contracor/boring	replace section of poly	
6/19/2018	218 Red Clover	Service	3/4"/1" galv	4.5	pinhole	replace galv/poly	topsoil
6/12/2018	1301-1311 Metaline	Service	2" galv	6.5	pinhole/split	replace galv/install reseter	topsoil

6/7/2018	1004 Main	Service	1"	5	pinhole	replace service line	flowfill
6/6/2018	261 Crook Ear	Service	1" Frost free		pinhole	turn off curb stop	
6/5/2018	Ontairo by 1207	Service	2" galv	5	p	wrap	Flowfill
6/5/2018	1606-1612 Hickory	Yoke	3/4 brass		split	replace yoke	topsoil
5/30/2018	Gooby & G.N.	Service	2"		2 day fix		
5/29/2018	Gooby & G.N.	Service	2" Galv	6	pinhole/deterioration	2" wrap, replace 2" stop	Flowfill
5/8/2018	702 Fir	Service	3/4 galv	6	pinhole	3/4 wrap	
5/8/2018	101 S. First	Service	3/4" galv	4.5	pinhole	wrap	topsoil
4/4/2018	1502 Larch	Service	1" cracked bushin	4	split/threads	replace bushing	topsoil
4/4/2018	1302 Kinniinck	Service	1" galv nip	4	pinhole	rebuild with brass	
3/21/2018	WWTP	Service	1 1/2	4	pinhole	1 1/2 wrap	dirt
3/14/2018	119 McGee Rd	Meter	1 1/2	2	Galv Bolts	SS Bolts	
1/18/2018	323 Lavina	Service	3/4 galv	4.5	pinhole	rebuild with brass	
1/17/2018	1111 Michigan	Service	3/4 galv	4.5	pinhole	wrap	
1/4/2018	31016 HWY 200	Service	1" IPS POLY	4	Contracor	nipp, female adpt	
	2017						
12/28/2017	500 Blk S Florance	LID	3/4 galv	3.5	Pinhole/Deterioration	Turn off at main	Flow fill
12/28/2017	Alley at Jeff/Hickory	LID	3/4 galv	5	Pinhole/Deterioration	Turn off at main	Flow fill
12/14/2017	East mountain veiw rd	Service	2" GALV	5.6	Pinhole/Deterioration	wraps	
12/6/2017	WWTP	Service	1 1/2 galv	4	Pinhole/Deterioration	wraps	
12/1/2017	127 S 1st	Service	1 1/2&2 galv	5	Pinhole/Deterioration	wraps	
11/28/2017	329 N Lincoln	Service	3/4 galv	4.5	Treads deterioration	rebuild with brass	
11/22/2017	Chestnut/Forrest	Main	16" streel	4	Pinhole/Deterioration	cover hole with tap saddle	Flow fill
11/21/2017	7 Alpine Dr.	Service	1/2 copper	4	split	brass parts	top soil
11/14/2017	314 S Lincoln	Service	3/4 galv	5	Pinhole/Deterioration	wrap	
11/8/2017	173 Kootnenai Meadow	Service	1" gavl	6	Pinhole/Deterioration	new meter, brass parts	
11/8/2017	10 kootenai Meadows Dr.	Service	1" galv	3	Pinhole/Deterioration	replace with 1 IPS	
11/6/2007	1114 Lake (Leao Hadey)	Service	2 inch galv	4.5	Pinhole/Deterioration	1" IPS, Replaced service line	Flow fill
11/2/2017	208 N 4TH	Service	1 galv	5	Pinhole/Deterioration	1" IPS/Meter,galv	Flow fill
10/16/2017	community garden Pine	LID	3/4 galv	4.6	Pinhole/Deterioration	Turn off at stop, copper to Mai	
10/3/2017	between 110&105 1st	Service	1" copper/galv	5	Barnacles	Turn off at stop, copper to Mai	
10/2/2017	123 S. 1ST	Service	1 poly	6	Barnacles	replace service line poly	top soil
9/21/2017	123 S. 1ST	Service	1 Gav	4	Pinhole/Deterioration	wrap	top soil
9/20/2017	245 Upperhumbird	Service	1 1/4 poly to gav	5	Pinhole/Deterioration	1" wrap	
8/23/2017	119 N. 1ST	Service	3/4 Bass	4	spit brass nipp	replace spit nipp	
8/15/2017	1115 Trainlge Dr.	Service	1 CTS POLY		Spit poly, bedding	sleve, nip, f. adpt.	

8/14/2017	1424 Baldy Rd.	Service	3/4 galv	4	corrosion	brass nip, comp coup	Flow fill
7/18/2017	511 Poplar St.	Service	3/4 galv	3.5	Pinhole/Deterioration	3/4 repair band	
7/5/2017	Charter School meter	Service	2" GALV	5	Pinhole/Deterioration	replace with 2 " poly	Flow fill
6/22/2017	716 Oak	Service	3/4 ploy	5	Pinhole/Deterioration	Brass nipp/comp coup	
6/22/2017	1000 Triangle Dr.	Service	1" CTS Poly	5.5	split pipe	1" st. ell, brass nipp, fem adp	
5/17/2017	2015 N Boyer	Service	2" galv	5	Pinhole/Deterioration	wrap	top soil
5/15/2017	505 Euclid	Service	1 CTS	4.5	Pinhole/Deterioration	brass nipple/CTS female	top soil
5/3/2017	S. Div & Lilly	Service	1 1/2 galv	4	Pinhole/Deterioration	wrap	Flow fill
4/25/2017	61 Whiskey Jack	Main	8 " cast	6	contractor	8" ss wrap	
4/24/2017	721 N Div.	Service	1 CTS	6	Hit By contractor	repair with Jumper	3/4 minus
4/11/2017	101 W Central(Kootenai)	Service	1" brass Sleave	5	split sleeve	replace with 3/4 comp coup	top soil
4/3/2017	2708 Boyer	Service	1 corp	5	corb split at main	install new one	Flow fill
3/7/2017	315 S Florance	Service	3/4 galv	3	Pinhole/Deterioration	Install stop	
2/21/2017	1730 Hickory	Service	1 galv	6	Pinhole/Deterioration	1 wrap	Flow fill
2/3/2017	621 Ruth	Main	6" cast	5	circlar crack	6" SS wrap	Flow fill
1/29/2017	2007 Sandpoint West Dr.	Service	2" pvc	5	Improper bedding	pvc parts	Flow fill
1/17/2017	711 Ruth	Main	6" cast	5	circlar crack	6" SS wrap	Flow fill
	2016						
12/19/2016	225 Cedar	Service	3/4 copper/brass	3.5	Split/Bedding	3/4 repair band	
12/5/2016	410 S. Florance	Service	3/4 galv		Spilt/Detective Pipe	Turn off corb @ main	
11/21/2016	1718 Janell	Service	3/4 galv stab in	5.5	Pinhole/Deterioration	brass stab in	
11/29/2016	1104 Elm	Main	6" Cast	4.5	Circum crack/???	6" SS repair band	
11/8/2016	1802 Megan	Service	1 1/2 Poly	5	Defective parts	female adpt.	
11/7/2016	1224 Michigan	Service	3/4 galv	4	Pinhole/Deterioration	2 3/4 wraps	
10/18/2016	WWTP	Service	1 1/4 galv	5	Pinhole/Deterioration	1 1/4 wrap	
5/22/2016	425 7th Ponderay	Main	6 cast	5	Circum split	6" repair Band	
9/29/2016	137 McGee Rd. Kootenai	Service	1" IPS	4	bedding	replace parts	
9/8/2016	363 4TH Ponderay	Service	3/4 galv	4	Pinhole/Deterioration	replace service w/poly	
7/20/2016	1011 Ruth	LID	3/4 galv	6.5	Pinhole/Deterioration	Turn off corb @ main	
7/11/2016	1200 Turbine	Main	8 pvc	4	contractor hit/loc off	replace sec of main	
6/28/2016	1110 Church	Service	3/4 galv	5	Pinhole/Deterioration	replace service	
6/27/2016	1411 Ontairo	LID	3/4 galv	4.5	Pinhole/Deterioration	Turn off corb @ main	
6/23/2016	599 Whiskey Jack Kootenai	Main	3 sch 40	5	Defective pipe	Replace parts connect service	
6/22/2016	1013 Pine st.	LID	3/4 galv	5	Pinhole/Deterioration	Turn off corb @ main	
6/6/2016	502 3rd(hospital)	Irrigation	3/4 galv	4	Pinhole/Deterioration	replace parts with brass	
5/31/2016	1119 Jefferson	Service	1 cts	5	Spilt/Detective Pipe	replace w/ips poly/parts	

5/26/2016	602 N. FIFTH(Mr Sub)	Service	2 poly	4.5	Spilt/Detective Pipe	replace sec of defect pipe	
5/17/2016	71 Knollwood Kootenai	Service	1 sch 40	5.5	Pinhole/Deterioration	replace parts with brass	
4/18/2016	1201-1207 Westwood Dr.	Meter	2"	4.7	Defective parts	replace flanges/bolts	
4/7/2016	2208 GN Road	Service	2 galve	4.5	Pinhole/Deterioration	2" wrap	
4/5/2016	407 & 407 1/2 S. Florance	Service	3/4 galv	4.6	Pinhole/Deterioration	replace service w/poly	
4/1/2016	514 Fir	Service	1 poly	5	Split/Defective Pipe	replace sec of poly	
3/30/2016	1912 Janelle	Service	3/4 poly/galv/pvc	4	Pinhole/Deterioration	replace parts with brass	
3/28/2016	Hwy 200 Johnson heating	Service	2" cts	5	split/improper beddin	replace parts	
3/21/2016	502 3rd	Irrigation	3/4 gav	4.5	Pinhole/Deterioration	replace w/ips poly/brass parts	
3/18/2016	909 Oak	Service	3/4 galv	4	Pinhole/Deterioration	replace parts with brass	
3/10/2016	542 Whiskey Jack Kootenai	Service	2" sch 40	4	Pinhole/Deterioration	replace parts/sch 40	
3/21/2016	429 S. Ella	Service	3/4 galv	5	Pinhole/Deterioration	3/4 wrap	
2/29/2016	515 Lavina	Service	3/4 galv	5.6	Pinhole/Deterioration	3/4 wrap	
2/27/2016	501 Bonner Mall	Service	1" Copper/galv	5	Pinhole/Deterioration	replace galv	flow fill
2/22/2016	4TH/OAK Ponderay	Main	6" cast	4.6	circum crack	1 6" SS rebar band	
1/29/2016	1024 Erie(meter @ 447 S. Ella	Service	3/4 galv	5	Pinhole/Deterioration	3/4 wrap	
	2015						
12/1/2015	606 S. Olive	Service	3/4 galv	4	Pinhole/Deterioation	3 Wraps	
11/27/2015	201 N. Division	Meter	2" Brass	6	Bolts/Gasket	new parts	
11/23/2015	196 Red Clover Kootenai	Service	3/4 galv	5	Pinhole/Deterioation	3/4 wrap	
11/15/2015	208 Church(Monark Coffee)	Service	1 CTS/IPS Poly	4	Defective pipe	new parts	
10/29/2015	1207 Michigan	Service	1 poly	4	Pinhole/Deterioation	replace galv nip/parts on yoke	
10/27/2015	517 Huron	Service	1 CTs	2.5	hit by Avista	new parts	
10/23/2015	89 McGee Kootenai	Service	1 IPS		Pinhole/Deterioation	new parts	
10/12/2015	1323 Michigan	Service	3/4 galv	4.5	Pinhole/Deterioation	3/4 wrap	
9/24/2015	Sandck Bridge	Main	8" cast	3	Joint leaking	1 8" 501 romac	
9/17/2015	105 Red Clover, Kootenai	Service	3/4 galv	5	Pinhole/Deterioation	3/4 wrap	
9/14/2015	417 W Lake	Service	3/4 galv	4.9	Pinhole/Deterioation	New Service	
9/2/2015	30196 Hwy 200 (Golf Course)	Main	8 " cast	6.6	circumferential	8" repair band	
8/28/2015	602 N Fifth (Mr Sub)	Service	2 poly	4	Split/Defective	replace sec of defect pipe	
8/25/2015	1605-1611 Westwood Dr	Service	1 thinwall poly	4.6	Defective pipe	replace parts with brass	
8/5/2015	422 S Boyer	Service	1 1/4 poly	3	Contrator hit	replace service	
8/3/2015	2415 N Boyer	Service	2 " galv		Pinhole/Deterioation	2" repair band	
7/22/2015	1204 Hickory (B)	Service	3/4 galv stab in		Pinhole/Deterioation	brass stab ins/parts	
7/13/2015	329 S Florence	Service	3/4 galv	4.6	Pinhole/Deterioation	3/4 wrap	
7/16/2015	West Wood East POOL	Service	2" pvc	5	Pinhole/Deterioation	2" nip/com-couplers	

7/15/2015	1302-1312 Westwood Court	Meter	2" galv	5	Pinhole/Deterioation	2" Wrap on home galv yoke	
6/17/2015	105 Secret Cove (Kootenai)	Service	2"	5	Split/Defective	replace parts with brass	
6/9/2015	819 Hwy 2 (meter on Superior)	Service	3/4 galv	7	Pinhole/Deterioation	replace service w/poly	
6/9/2015	1205 Alder (meter on Jeffer)	Service	3/4" galv	6	Treads/Corrosion	replace galv	
5/6/2015	21 Spur Dr. Kootenai	Service	3/4 sch 40	4	Defective pipe	3/4 wrap	
5/6/2015	206 Boise (Kootenai)	Service	3/4 sch 40	5	Pinhole/Deterioation	replace parts with brass	
5/5/2015	606 Jefferson	Service	1 cts/galv parts	5	Pinhole/Deterioation	replace galv parts w/ brass	
5/5/2015	1001 Forrest	Service	3/4 galv	5	Pinhole/Deterioation	3/4 wrap	
4/1/2015	614 Madison	Service	1 1/2 galv	4	Pinhole/Deterioation	1 1/2 Wrap	
3/17/2015	315 S Ella	Service	3/4 galv		Pinhole/Deterioation	replace service w/poly	
2/27/2015	2703 N Boyer	Service	1" thin wall	4.6	Split/Defective	1" stab-in	
2/13/2015	1008 Superior	Service	LID	6.6	Defective pipe	Turn off corb @ main	
2/12/2015	502 N 2nd	Service	3/4 copper	4.6	Contrator hit	brass parts	
2/4/2015	1214 Church	Service	3/4 galv	4	big hole/deterioration	3/4 wrap	
1/28/2015	512 St. Clair	Service	3/4 galv	5	Split/Defective	replace parts with brass	
1/23/2015	2025 Sandpoint West Dr	Service	2" PVC	5	Split/Defective	pvc parts	
1/7/2015	437 Cedar (Ponderay Fire House)	Service	2 cst poly	5	Split/Defective	brass parts	
	2014						
12/22/2014	429 S Ella	Service	3/4 galv	5	Pinhole/Deterioration	3/4 wrap	
10/14/2014	1100 Blk Oak St	Service	3/4 galv	6	Pinhole/Deterioration	3/4 wrap	
9/29/2014	GN, 600 ft S of Woodland	Main	16 steel	5	Leakly Joint	bell joint restainer	
9/16/2014	1809 Poplar	Service	1 cts	5	Pinhole/Deterioration	replace galv parts	
9/15/2014	608 Lakeveiw	Service	3/4 galv	4	Pinhole/Deterioration	Brass parts	
9/2/2014	1200 Blk of Oak, G Trailers	Service	2" Galv Manifold	5	Pinhole/Deterioration	2" Wrap	
8/28/2014	117 S Lincoln, apartments	Meter	2 fitting	5	Deterioration	Brass parts	
7/31/2014	714 Hickory	Service	3/4 galv	6	Pinhole/Deterioration	3/4 wrap	
7/22/2014	1102 Ruth	Service	3/4 galv	5	Pinhole/Deterioration	2 3/4 wraps	
7/22/2014	1002 Chestnut	Service	3/4 galv	6	Pinhole/Deterioration	2 3/4 wraps	
7/7/2014	1730 Hickory	Service	1 galv	5	Pinhole/Deterioration	1 wrap	
6/11/2014	620 Superior	Service	1 cts to ips	4.6	wrong parts/split	right parts	
6/2/2014	108 Humbird (Kootenai)	Service	3/4 galv	4	Pinhole/Deterioration	Brass parts	
5/14/2014	513 Poplar	Service	2 galv	2.6	Pinhole/Deterioration	2 Wrap	
4/21/2014	63 U Humbird (Kootenai)	Service	1 1/4 galv	5.6	Pinhole/Deterioration	1 1/4 wrap	
4/9/2014	1800 GN Road	Service	thin wall poly	4	improper bedding	replace with new ploy	
4/3/2014	409 S Florence	Service	3/4 galv	5	Pinhole/Deterioration	replace service w/poly	
4/3/2014	908 Cedar	Service	3/4 galv	5	Pinhole/Deterioration	replace service w/poly	

3/19/2014	514 Oak	Service	1 galv	4.5	Pinhole/Deterioration	replace 4' w/poly, rest galv	
3/19/2014	500 Blk Fir	LID				Turn off corp @ main	
3/13/2014	35 Jeffrey Dr (Kootenai)	Service	1" galv	4	Pinhole/Deterioration	replace service w/poly	
3/14/2014	417 Lake	Service	3/4 galv	5	Pinhole/Deterioration	Turn off corp @ main	
2/21/2014	1211-17 Main, 1208 Alder	Service	2" galv	4.5	Pinhole/Deterioration	replace galv	
1/24/2014	1312 Red Clover (Kootenai)	Service	3/4 galv	4.5	Pinhole/Deterioration	replace parts with brass	
1/22/2014	326 St. Clair	Main	6" cast	4.5	circler at corp	6" SS Wrap	
1/4/2014	119 McGee (Kootenai)	Meter	2"	3	Deterioration	new bolts/gaskets	
	2013						
11/18/2013	212 N First	Service	2 galv	6	Pinhole/Deterioration	2 2" wraps	
11/21/2013	1220 Superior	Service	3/4 galv	5.6	Pinhole/Deterioration	3 3/4 wraps	
11/6/2013	300-400 Blk Dalby Dr	Service	3/4 galv	6	Pinhole/Deterioration	3/4 wrap	
11/2/2013	115 Garden Ave (Kootenai)	Service	3/4 galv	6	Pinhole/Deterioration	3/4 wrap	
10/14/2013	719 Cedar	Service	3/4 galv	4	Split/Corrosion	3/4 wrap	
10/13/2013	205 Main (Kootenai)	Service	3/4 galv	3.25	split/bedding	2 3/4 wraps	
9/4/2013	1802 Janelle	Service	3/4 poly/pvc	4	Pinhole/Deterioration	replace galv/pvc parts w/brass	
8/19/2013	1319 Larch	Service	3/4 galv	7+	Pinhole/Deterioration	Turn off corb @ main	
8/8/2013	502 N Lincoln	Service	1 galv nipple	4	Pinhole/Deterioration	replace w/brass	
8/5/2013	1310 Main	Service	3/4 galv	4.5	Pinhole/Deterioration	replace service w/poly	
7/18/2013	GN/Woodland	Service	3/4 galv	4	Pinhole/Deterioration	Turn off stop at main	
7/9/2013	1100 Blk N. Boyer	Main	16/14 Steel	4	Pinhole/Deterioration	Tapping saddle w/plug	
6/24/2013	1502 Hemlock	Service	1 poly/galv	7	Threads/Deterioration	bass nip/ 1x12 resetter	
5/16/2013	1100 Blk Pine St	LID	3/4 galv	4.4	Derteriation	Turn off corb @ main	
5/2/2013	111 Lower Humbird (Kootenai)	Service	3/4 galv	5.6	Pinhole/Deterioration	2 3/4 wraps	
4/4/2013	1400 Blk Walnut (Life Care)	Meter	2" parts	4	Derteriation	replace bolts/flanges	
4/8/2013	1014 Oak	Service	3/4 galv	4	Derteriation	3/4 repair bands	
2/13/2013	820 Larch	Service	3/4 galv	6	Pinhole/Deterioration	3/4 Wrap	
1/14/2013	637 Oak (Ponderay)	Service	1" poly	4+	split/defective pipe	Brass parts	
1/11/2013	301 S. Ella	Service	1 galv	5	Pinhole/Deterioration	1 wrap	
1/11/2013	305 Main (Kootenai)	Service	3/4 galv	4	Pinhole/Deterioration	3/4 wrap	